

WILSONVILLE, CONNECTICUT
FRENCH RIVER

LANGERS POND DAM
CT-00186

**The original hardcopy version of this report
contains color photographs and/or drawings.
For additional information on this report
please email**

**U.S. Army Corps of Engineers
New England District
Email: Library@nae02.usace.army.mil**

**NATIONAL DAM INSPECTION PROGRAM
CORPS OF ENGINEERS**

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER CT 00186	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Langers Pond Dam NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS		5. TYPE OF REPORT & PERIOD COVERED INSPECTION REPORT
		6. PERFORMING ORG. REPORT NUMBER
7. AUTHOR(s) U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION		8. CONTRACT OR GRANT NUMBER(s)
9. PERFORMING ORGANIZATION NAME AND ADDRESS		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
11. CONTROLLING OFFICE NAME AND ADDRESS DEPT. OF THE ARMY, CORPS OF ENGINEERS NEW ENGLAND DIVISION, NEDED 424 TRAPELO ROAD, WALTHAM, MA. 02254		12. REPORT DATE Feb. 1980
		13. NUMBER OF PAGES 35
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMITED		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES Cover program reads: Phase I Inspection Report, National Dam Inspection Program; however, the official title of the program is: National Program for Inspection of Non-Federal Dams; use cover date for date of report.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) DAMS, INSPECTION, DAM SAFETY, Wilsonville Conn. French River Langers Pond Dam		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) Langers Pond Dam is a 10.5 foot high, "L-shaped", run-of-the-river stone masonry gravity structure. It is 160 feet in length, and constructed of stone masonry with a concrete section along the upstream face. Based upon the visual inspection the project appears to be in good condition.		

INSPECTION REPORT
LANGERS POND DAM
CT 00186

Langers Pond Dam is a 10.5 foot high, "L-shaped", run-of-the-river stone masonry gravity structure. It is located on the French River in Wiltonville, Connecticut and owned by the Simonds Company, also of Wiltonville. The dam was constructed in 1880 to supply water for the generation of power for the mill at the dam, now the Simonds Company. In recent times, the power generating facilities have been inoperable, however, the present owner is in the process of restoring these facilities. The drainage area is approximately 97 square miles and the maximum impoundment to the top of the dam is 156 acre-feet.

Because the dam is a run-of-the-river structure, the entire length of the dam is used as a spillway. It is 160 feet in length, and constructed of stone masonry with a concrete section along the upstream face. The concrete section is 15 inches wide and forms the crest of the dam at elevation 383.0. The stone masonry section is about 4.5 to 5 feet wide at the top (elevation 381.0), 11 feet wide at the base (elevation 372.5), and has a stepped downstream face. The training wall at the left end of the dam is about 3.5 feet above the dam crest and is constructed of stone and mortar masonry. At the right end, the dam abuts the concrete foundation of one of the Simonds Company buildings.

There is no low-level outlet at the dam. The only method of releasing water, other than over the dam, is through the channel which was once used to supply water for generating purposes. However, at this time the channel is almost completely filled in and the gates of the upstream end are severely deteriorated.

For the owner's information and use, the following items are attached in duplicate:

1. Hydraulic/Hydrologic Computations
2. General Plan w/Typical Section and Profile
3. Photographs
4. Visual Inspection Check List




Based upon the visual inspection, the project appears to be in good condition. The following features which could influence the future condition and/or stability were identified.

1. Stones appear to have become dislodged from the downstream face at the left side of the dam (Photo 1). If not repaired, more stone may become dislodged, leaving a weak zone in this area and possibly leading to failure of the structure.
2. The downstream end of the left training wall needs repair. The wall in this area is broken up and falling into the channel. If not repaired, undermining of the left abutment may occur during high flows, leading to gradual undermining and possible failure of the left side of the dam.
3. There is no low-level outlet at the dam. However, if the existing sluice way and gates are repaired, this should provide a sufficient outlet.

The owner should retain a registered professional engineer qualified in dam design and inspection to perform services pertaining to the following items. The engineer should establish correction measures which should then be instituted by the owner.

1. An attempt should be made to inspect the dam during period of low flow, so a more detailed inspection can be performed.
2. Recommendations should be made for repair of the downstream face of the dam and the left training wall.
3. The stone masonry should be repointed if the more detailed inspection reveals the need for this repair.

Also, the owner should insure that the crest of the dam and the channel at the toe of the dam remain clear of debris.



OVERVIEW PHOTO
(February, 1980)

US ARMY ENGINEER DIV. NEW ENGLAND
CORPS OF ENGINEERS
WALTHAM, MASS.

NATIONAL PROGRAM OF
INSPECTION OF
NON-FED DAMS

Langers Pond Dam

Wilsonville

DATE Dec. 1980

CAHN ENGINEERS INC.
WALLINGFORD, CONN.
ENGINEER

French River

CONNECTICUT

CE # 27 785 KF

PAGE ix



Photo 1-Crest and downstream face of dam from the fill by the outlet channel at the right end of the dam. Note displacement of stones at left end of dam (Dec. 1980).




Photo 2 - Embankment and opening at road just upstream from dam (Dec. 1980).

US ARMY ENGINEER DIV. NEW ENGLAND
CORPS OF ENGINEERS
WALTHAM, MASS.

CAHN ENGINEERS INC.
WALLINGFORD, CONN.
ENGINEER

NATIONAL PROGRAM OF
INSPECTION OF
NON-FED. DAMS

Langers Pond Dam
French River
Wilsonville, CT

CE# 27 785 KF
DATE Dec. 1980 PAGE 0




Photo 3 - Downstream face of dam where it abuts factory foundation at right end of dam (Dec. 1980).



Photo 4 - Masonry training wall and downstream face of dam at left end. Masonry retaining or cut-off wall at right side of photo in background (Dec. 1980).

US ARMY ENGINEER DIV. NEW ENGLAND
CORPS OF ENGINEERS
WALTHAM, MASS.

CAHN ENGINEERS INC.
WALLINGFORD, CONN.
ENGINEER

NATIONAL PROGRAM OF
INSPECTION OF
NON-FED. DAMS

Langers Pond Dam

French River

Wilsonville, CT

CE# 27 785 KF

DATE Dec. 1980 PAGE C-7




Photo 5 - Gate hoists and remains of wooden gates. The fill placed across the upstream end of the outlet channel is barely visible at lower right (Dec. 1980).




Photo 6 - Outlet channel from downstream. Gate hoists are visible in background, fill just above building housing the turbine is visible at lower left (Dec. 1980).

US ARMY ENGINEER DIV. NEW ENGLAND
CORPS OF ENGINEERS
WALTHAM, MASS.

CAHN ENGINEERS INC.
WALLINGFORD, CONN.
ENGINEER

NATIONAL PROGRAM OF
INSPECTION OF
NON-FED. DAMS

Langers Pond Dam

French River

Wilsonville, CT

CE# 27 785 KF

DATE Dec. 1980 PAGE C




Photo 7 - Abandoned turbine looking downstream from fill in outlet channel. Drain holes in floor of concrete structure, allow water seeping through fill to flow back to the river,




Photo 8 - Outlet Channel taken from top of concrete structure containing turbine. Openings at base of building to the left are for turbine which no longer exists (Dec. 1980).

US ARMY ENGINEER DIV. NEW ENGLAND
CORPS OF ENGINEERS
WALTHAM, MASS.

CAHN ENGINEERS INC.
WALLINGFORD, CONN.
ENGINEER

NATIONAL PROGRAM OF

INSPECTION OF
NON-FED. DAMS

Langers Pond Dam

French River

Wilsonville, CT

CE# 27 785 KF

DATE Dec. 1980 PAGE C-4

INSPECTION CHECK LIST
CITY ORGANIZATION

PROJECT Wardens in

DATE: December 1, 1980

TIME: 10:00 AM to 1:00 PM

WEATHER: Sunny, 50°F

W.S. ELEV. 333.2 U.S. DN.S

PARTY:

INITIALS:

DISCIPLINE:

- | <u>PARTY:</u> | <u>INITIALS:</u> | <u>DISCIPLINE:</u> |
|---------------------------|------------------|--------------------------|
| 1. <u>Peter M. Heyner</u> | <u>PMH</u> | <u>Cahn-Geotechnical</u> |
| 2. <u>Jay A. Costello</u> | <u>JAC</u> | <u>Cahn-Geotechnical</u> |
| 3. <u>Frank Segoline</u> | <u>ES</u> | <u>Cahn-Survey</u> |
| 4. <u>Murali Aturu</u> | <u>MA</u> | <u>DTC-H/H</u> |
| 5. _____ | _____ | _____ |
| 6. _____ | _____ | _____ |

PROJECT FEATURE

INSPECTED BY

REMARKS

- | <u>PROJECT FEATURE</u> | <u>INSPECTED BY</u> | <u>REMARKS</u> |
|------------------------|-------------------------|----------------|
| 1. <u>SPILLWAY</u> | <u>PMH, JAC, MA, ES</u> | <u>A-2</u> |
| 2. _____ | _____ | _____ |
| 3. _____ | _____ | _____ |
| 4. _____ | _____ | _____ |
| 5. _____ | _____ | _____ |
| 6. _____ | _____ | _____ |
| 7. _____ | _____ | _____ |
| 8. _____ | _____ | _____ |
| 9. _____ | _____ | _____ |
| 10. _____ | _____ | _____ |
| 11. _____ | _____ | _____ |
| 12. _____ | _____ | _____ |

PERIODIC INSPECTION CHECK LIST

Page 4-2

PROJECT Harper Pond Dam

DATE Dec 3, 1982


PROJECT FEATURE Spillway

BY W. J. Taylor

AREA EVALUATED	CONDITION
<p><u>OUTLET WORKS-SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS</u></p> <p>a) <u>Approach Channel</u></p> <p>General Condition</p> <p>Loose Rock Overhanging Channel</p> <p>Trees Overhanging Channel</p> <p>Floor of Approach Channel</p> <p>b) <u>Weir and Training Walls</u></p> <p>General Condition of Concrete</p> <p>Rust or Staining</p> <p>Spalling</p> <p>Any Visible Reinforcing</p> <p>Any Seepage or Efflorescence</p> <p>Drain Holes</p> <p>c) <u>Discharge Channel</u></p> <p>General Condition</p> <p>Loose Rock Overhanging Channel</p> <p>Trees Overhanging Channel</p> <p>Floor of Channel</p> <p>Other Obstructions</p>	<p>Appears good, clear</p> <p>} None observed</p> <p>Silted in, sand & gravel</p> <p>Concrete - good</p> <p>stone masonry - needs repair left end. stones dislodged. rest training wall needs repair.</p> <p>} None observed</p> <p>N/A</p> <p>fair</p> <p>} None observed</p> <p>Some stones, wood debris</p> <p>N/A</p>

PROJECT NON FEDERAL DAM INSPECTION PROJECT NO. 90-10-19 SHEET 1 OF 14
NEW ENGLAND DIVISION COMPUTED BY [Signature] DATE 12/18/80
LANGERS POND DAM CHECKED BY E. Butcher Balon DATE 12/19/80

SPILLWAY CREST ELVD = 383 NGVD*
 TOP OF THE DAM EL = 386.5 (ELVN OF THE LEFT ABUTMENT - CONCRETE WALL)
 TOP OF THE DAM EL = 372.5
 HEIGHT OF THE DAM = 14 FT (4c)




APPROXIMATE POTENTIAL OVERFLOW PROFILE
 (BASED UPON CAHN INC'S FIELD INFORMATION)

STORAGE

PLANIMETERING FROM USGS MAP FOR POND SURFACE AREAS:
 AT EL. 383 (SPILLWAY CREST) = 18 AC.

AT EL. 390 = 31 AC.



A STAGE-POND AREA CURVE IS PLOTTED.

POND AREA AT TOP OF DAM = 35 AC.

AVERAGE POND AREA BET. SP. CR. & TOP OF DAM = $\frac{18+35}{2} = 26.5 AC$

STORAGE BETWEEN SP. CREST & TOP OF DAM = $3.5 \times 26.5 = 93 AC \cdot FT$

STORAGE BELOW SP. CREST = $\frac{1}{3} \times 18 \times 10.5 = 63 AC \cdot FT$

∴ MAXIMUM IMPOUNDMENT TO TOP OF DAM = $93 + 63 = 156 AC \cdot FT(S)$

* THE W.S. ELVN OF 383 MSL ON THE WEBSTER, MASS USGS QUAD SHEET (1969) IS ASSUMED TO BE THE SPILLWAY CREST ELVD ON NATIONAL GEODETIC VERTICAL DATUM (NGVD). ALL OTHER ELVNS ARE REFERENCED TO THIS ASSUMED ELVN AND ARE OBTAINED BASED UPON INFORMATION FURNISHED BY CAHN, INC.

SHEET 2 OF 14

W. L. ...

12/18/80

E. Butler Bolton 12/19/80

SURFACE AREA ACRES

60 45 30 15 0

400

395


390

395

390

ELEVATION IN FEET

LANGERS POND DAM



D. 2

PROJECT NON FEDERAL DAM INSPECTION PROJECT NO. 80-10-19 SHEET 3 OF 14
NEW ENGLAND DIVISION COMPUTED BY [Signature] DATE 12/18/80
LANGERS POND DAM CHECKED BY E. Butcher Balun DATE 12/19/80

BREACH ANALYSIS

DOWNSTREAM FAILURE HAZARD:

BREACH OUTFLOW $Q_b = \frac{8}{27} W_b \sqrt{g} Y_o^{3/2}$ BASED UPON CORPS OF ENGINEERS "RULE OF THUMB" GUIDANCE FOR ESTIMATING DIS DAM FAILURE HYDROGRAPHS

ESTIMATED BREACH WIDTH = 40% OF MID-HEIGHT LENGTH OF DAM

MID-HEIGHT LENGTH IS ASSUMED = LENGTH OF THE SPILLWAY FOR LACK OF OTHER DATA

\therefore BREACH WIDTH = 160 FT.
 $= 0.4 \times 160 = 64$ FT.

$Q_b = \frac{8}{27} \times 64 \sqrt{32.2} \times (14)^{3/2} = 5640$ CFS


PEAK FAILURE OUTFLOW $Q_p = Q_b +$ DISCHARGE OVER UNBREACHED LENGTH OF THE SPILLWAY

UNBREACHED LENGTH OF SPILLWAY = 160' - 64' = 96'

$Q_{sp} = C L H^{3/2}$

FOR BROAD CRESTED CONCRETE SPILLWAY WITH U/S FACE ASSUMED VERTICAL $C = 3.5$ USED

(REF. USGS BOOK 3, CHAPTER A 5, FIGURE 7, P. 10 - MEASUREMENT OF PEAK DISCHARGE AT DAM BY INDIRECT METHODS)



$Q_{sp} = 3.5 \times 96 \times (3.5)^{3/2}$ FOR POOL AT TOP OF DAM
 $= 2200$ CFS

PEAK FAILURE OUTFLOW $Q_p = 5640 + 2200 = 7840$ CFS

ESTIMATED FAILURE FLOOD DEPTH IMMEDIATELY D/S FROM DAM = $0.44 \times Y_o$
 $= 0.44 \times 14 = 6.2$ FT.

(NOTE: THE TAILWATER EFFECT DUE TO NORTH GROSVEGNORDALE POND LOCATED D/S DOES NOT APPEAR TO INFLUENCE THIS ANALYSIS)

PROJECT NON FEDERAL DAM INSPECTION PROJECT NO. 80-10-19 SHEET 4 OF 14
NEW ENGLAND DIVISION COMPUTED BY Chand Jha DATE 12/18/80
LANGERS POND DAM CHECKED BY E. Butulu Babu DATE 12/19/80

PERFORM DIS ROUTING OF PEAK FAILURE OUTFLOW
 SELECT A SECTION AA 300' DIS OF THE DAM. THIS SECTION IS SELECTED TO ESTIMATE POSSIBLE FLOODING DAMAGE TO THE MANUFACTURING FACILITY (SIMONDS CO) USING MANNING'S EQUATION

$$Q = \frac{1.486}{n} \times A \times R^{2/3} \times A^{1/2}$$

$n = 0.06$ ASSUMED (STONES)
 $\lambda = 0.0016$ FROM USGS MAP

$$= \frac{1.486}{0.06} \times A \times R^{2/3} \times (0.0016)^{1/2}$$

$$= 1.0 \times A \times R^{2/3}$$

RIVER BED ELEVN AT SECTION AA = 372 (BASED UPON $\lambda = 0.0016$)

ELVN	A SQ. FT	P	R = A/P	R ^{2/3}	Q CFS
372	0	-	-	-	0
374	64	63.7	1.0	1.0	64
376	253	126.8	2.0	1.59	402
378	565	188.9	2.99	2.08	1175
380	1000	250.5	3.99	2.52	2520
382	1412	283.2	4.99	2.92	4123
384	1884	314.9	5.98	3.30	6217
386	2415	346.1	6.98	3.65	8815

STAGE-AREA AND STAGE DISCHARGE CURVES ARE PLOTTED FOR SECTION AA
 FOR PEAK FAILURE OUTFLOW $Q_{P1} = 7840$ CFS,
 ELVN = 385.2 FROM STAGE DISCHARGE CURVE.
 FROM STAGE-AREA CURVE AREA = 2188 SQ. FT

VOLUME OF REACH $V_1 = \frac{300 \times 2188}{43.560} = 15$ AC. FT.

TRIAL $Q_{P2} = Q_{P1} \left(1 - \frac{V_1}{S}\right)$, WHERE S = STORAGE TO TOP OF DAM


$$= 7840 \left(1 - \frac{15}{156}\right) = 7080$$
 CFS.

Invd. by

12/18/80

E. Buteh Babu 12/19/80

LANGERS POND
STAGE AREA CURVE
300 FT. D/S OF DAM



HORIZONTAL DISTANCE IN FEET

LOOKING DOWNSTREAM
SECTION A-A

U.S.


SHEET 6 OF 14

And dm 12/16/20

E. Bitchu Babu 12/19/20

LANGERS POND
STAGE DISCHARGE CURVE

DISCHARGE IN CFS
SECTION AA



D-6

PROJECT NON FEDERAL DAM INSPECTION PROJECT NO. 80-10-19 SHEET 7 OF 14
 NEW ENGLAND DIVISION COMPUTED BY And. Jmy DATE 12/18/80
 LANGERS POND DAM CHECKED BY E. Butcher Palen DATE 12/19/80

FOR THIS Q_{PE} , THE STAGE DISCHARGE CURVE GIVES
 ELVN = 384.6 AND AREA = 2035 SQ. FT.
 $V_2 = \frac{300 \times 2035}{43.560} = 14 \text{ AC. FT.}$

RECOMPUTING $Q_{PE} = 7840 \left(1 - \frac{14.715}{2}\right) = 7110 \text{ CFS}$

FLOOD STAGE AT SECTION AA = EL. 384.6
 FLOOD DEPTH AT SECTION AA = EL. 384.6 - EL. 372 = 12.6 FT.
 AND VELOCITY AT SECTION AA = $\frac{7110}{2035} = 3.5 \text{ FPS}$

THE 1ST FLOOR OF SIMONDS CO MANUFACTURING FACILITY IS AT LEAST 2 FT ABOVE THIS FLOOD STAGE OF 384.6.


SELECT A SECTION BB 340' DIS OF AA
 BED ELVN AT BB = EL. 372.5 $340 \times .0016 = 371.5$

USING MANNING'S EQUATION:
 $Q = \frac{1.486}{n} \times A \times R^{2/3} \times S^{1/2}$ $n = 0.06 \text{ ASSUMED}$
 $R = \frac{1.0}{S} \times A \times R^{2/3}$ $S = 0.0016 \text{ (USGS MAP)}$


ELVN	A SQ. FT.	P	R = A/P	R ^{2/3}	Q CFS
371.5	0	-	-	-	0
374	219	175.1	1.25	1.16	254
378	1511	465.2	3.25	2.2	3324
380	2614	615.2	4.25	2.62	6862
382	3859	735.2	5.25	3.02	11654

STAGE AREA AND STAGE DISCHARGE CURVES ARE PLOTTED FOR SECTION BB
 FOR PEAK OUTFLOW $Q_{PE} = 7110 \text{ CFS}$, ELVN = 380.2
 AND AREA = 2767 SQ. FT.

SHEET 8 OF 14
Langer's Pond 12/18/80
E. Butcher Baber 12/19/80



SHEET 9 OF 14
Dred. Draw 12/11/80
E. Butcher Babu 12/19/80



D-9

PROJECT NON FEDERAL DAM INSPECTION PROJECT NO. 80-10-19 SHEET 10 OF 14
NEW ENGLAND DIVISION COMPUTED BY hmd:dmz DATE 12/12/80
LANGERS POND DAM CHECKED BY E. Buttili, Balu DATE 12/19/80

VOLUME OF REACH $V_1 = \frac{340 \times 2767}{43.560} = 21.6 \text{ AC.FT.}$

STORAGE REMAINING $= (156 - 14.15) = 141.5 \text{ AC.FT.}$

TRIAL $Q_{P2} = Q_{P1} \left(1 - \frac{V_1}{S}\right)$

$= 7110 \left(1 - \frac{21.6}{141.5}\right) = 6025 \text{ CFS}$

FOR THIS Q_{P2} , ELVN $= 379.6$ AND AREA $= 2365 \text{ SQ.FT.}$

$V_2 = \frac{340 \times 2365}{43.560} = 18.5 \text{ AC.FT.}$

RECOMPUTING $Q_{P2} = 7110 \left(1 - \frac{21.6 + 18.5}{2 \times 141.5}\right) = 6100 \text{ CFS}$

FLOOD STAGE AT SECTION BB $= 379.6$

FLOOD DEPTH AT SECTION BB $= 379.6 - 371.5 = 8.1 \text{ FT.}$

AND VELOCITY AT SECTION BB $= \frac{6100}{2365} = 2.6 \text{ FPS}$

SELECT A SECTION CC 1290' DIS OF BB

BED ELVN @ SECTION CC $= 372.5 - 1930 \times .0016 = 369.4$

USING MANNING'S EQUATION

$Q = \frac{1.486}{m} \times A \times R^{2/3} \times S^{1/2}$
 $= 0.74 \times A \times R^{2/3}$

$m = 0.08$ ASSUMED
 $S = .0016$ (USGS MAP)

STORAGE REMAINING $= 141.5 - \frac{21.6 + 18.5}{2} = 121.5 \text{ AC.FT.}$

ELVN	A SQ.FT.	P	R = A/P	$R^{2/3}$	Q CFS
369.4	0	-	-	-	0
372	442	340	1.3	1.2	312
374	1380	600.2	2.3	1.74	1777
376	2971	870.2	3.3	2.22	4716
378	4833	1124.3	4.3	2.64	9442

PROJECT NON FEDERAL DAM INSPECTION PROJECT NO. 80-10-19 SHEET 11 OF 14
NEW ENGLAND DIVISION COMPUTED BY And. J. W. DATE 12/18/80
LANGERS POND DAM CHECKED BY E. Butler Baber DATE 12/19/80

STAGE AREA AND STAGE DISCHARGE CURVES ARE PLOTTED FOR SECTION CC.

FOR PEAK OUTFLOW $Q_1 = 6100 \text{ CFS}$, ELVN = 376.6
 AND AREA = 3398 SQ. FT.

VOLUME OF REACH $V_1 = \frac{1290 \times 3398}{43.560} = 100.6 \text{ AC. FT.}$

TRIAL $Q_2 = Q_1 \left(1 - \frac{V_1}{S}\right)$
 $= 6100 \left(1 - \frac{100.6}{121.5}\right) = 1049 \text{ CFS}$

FOR THIS Q_2 , ELVN = 373.2, AREA = 950 SQ. FT.

$\therefore V_2 = \frac{1290 \times 950}{43.560} = 28 \text{ AC. FT.}$

RECOMPUTING $Q_2 = 6100 \left(1 - \frac{100.6 + 28}{2}\right)$
 $= 2870 \text{ CFS}$

FLOOD STAGE AT SECTION CC = 373.2

FLOOD DEPTH AT SECTION CC = 373.2 - 369.4 = 3.8 FT.


AND VELOCITY AT SECTION CC = $\frac{2870}{950} = 3.0 \text{ FPS}$

STORAGE VOLUME REMAINING = $121.5 - \frac{100.6 + 28}{2}$

= 57 AC. FT.

SHEET 12 OF 14
Amly dh
E. Butcher Babu 12/18/80
12/19/80

LANGERS POND
STAGE AREA CURVE




HORIZONTAL DISTANCE IN FEET
LOOKING DOWNSTREAM
SECTION CC

ELEVATION IN FEET

H-12

SHEET 13 OF 14
hml dh 12/18/80
E. Butcher Baber 12/19/80



D-13

PROJECT NON FEDERAL DAM INSPECTION PROJECT NO. 80-10-19 SHEET 14 OF 14
NEW ENGLAND DIVISION COMPUTED BY [Signature] DATE 12/18/80
LANGERS POND DAM CHECKED BY [Signature] DATE 12/19/80

FAILURE HAZARD POTENTIAL

THE FAILURE ANALYSIS WAS DONE WITH POOL AT TOP OF DAM (EL. 386.5 NGVD).

SUMMARY OF BREACH ANALYSIS RESULTS:

LOCATION	DISTANCE FROM DAM FT.	PEAK FLOW RATE CFS	FLOOD STAGE	FLOOD DEPTH FT.	VELOCITY FPS	STORAGE REMAINING AC. FT.
DAM	0	7840	378.7	6.2	—	156
AA	300	7110	384.6	12.6	3.5	141.5
BB	640	6100	379.6	8.1	2.6	121.5

AT SECTION AA, THE FLOOD STAGE IS 384.6 WHEREAS THE 1ST FLOOR ELEVATION OF SIMONDS MANUFACTURING BUILDING IS 386.6. HOWEVER, THE LOWER FLOOR OF THE BUILDING ADJACENT TO THE RIVER COULD BE SUBJECT TO FLOOD DAMAGE. ALSO, THE RAILROAD TRACKS COULD BE INUNDATED IN THE VICINITY OF SECTION AA. BETWEEN SECTION AA AND CC, NO OTHER STRUCTURE IS LIKELY TO BE FLOODED.

THE REMAINING STORAGE VOLUME OF 57 AC. FT. AT SECTION CC WOULD BE ATTENUATED IN THE NORTH GROSVENORDALE POND (60 AC) WITH A RISE OF WATER ELEVATION BY LESS THAN 1 FT. IN THE POND.

THUS DUE TO DAM FAILURE SOME ECONOMIC LOSS, PRIMARILY AT SIMONDS CO. COULD BE EXPECTED. HOWEVER, LOSS OF LIFE FROM DAM FAILURE IS UNLIKELY THEREFORE, THE LANGERS POND DAM IS CLASSIFIED AS A "LOW" HAZARD POTENTIAL DAM.

IDENTIFICATION	DIVISION	STATE	COUNTY	COUNTY CODE	STATE CODE	COUNTY CODE	CONCRETE	NAME	LATITUDE		LONGITUDE		REPORT DATE			
									N	W	E	S	DAY	MO	YR	
1	VT	VT	FRANKLIN	001	VT	FRANKLIN	001	LANGERS FUND DAM	43	00	71	52	23	1	DEC	80

IDENTIFICATION	POPULAR NAME	NAME OF IMPOUNDMENT
1	LANGERS FUND	LANGERS FUND

LOCATION	REGION	BASIN	RIVER OR STREAM	NEAREST DOWNSTREAM CITY - TOWN - VILLAGE	DIST FROM DAM (MI)	POPULATION

STATISTICS	TYPE OF DAM	YEAR COMPLETED	PURPOSES	STRUCTURAL HEIGHT (FT)	HYDRAULIC HEIGHT (FT)	IMPOUNDING CAPACITIES		CORPS ENGR. DIST.	CORP. UN. NO.	FED. RES. NO.	VERIFICATION DATE	BLANK	
						MAXIMUM (ACR - FT)	NORMAL (ACR - FT)						
1	CONCRETE	1966	HYDROELECTRICITY	116	116	196	196	1	1	1	31	DEC	80

REMARKS
LOCAL ROAD WITH CONCRETE OUTLETS ALONG DOWNSTREAM FACE

ENG 12/77 4474

STATISTICS	CREST LENGTH (FT)	SPILLWAY		VOLUME OF DAM (CU YD)	POWER CAPACITY								BLANK	
		INSTALLED (KW)	PROPOSED (KW)		LENGTH (FT)	WIDTH (FT)	LENGTH (FT)	WIDTH (FT)	LENGTH (FT)	WIDTH (FT)	LENGTH (FT)	WIDTH (FT)		
5	160	100	100	75000	100	100	100	100	100	100	100	100	100	100

MISC DATA	OWNER	ENGINEERING BY	CONSTRUCTION BY
6	STANBIS COMPANY		

MISC DATA	DESIGN	CONSTRUCTION	OPERATION	MAINTENANCE
7	ENVIRONMENTAL PROTECT	ENVIRONMENTAL PROTECT	ENVIRONMENTAL PROTECT	ENVIRONMENTAL PROTECT

MISC DATA	INSPECTION BY	INSPECTION DATE	AUTHORITY FOR INSPECTION
8	PAK ENGINEER, INC.	01 DEC 80	PAK

REMARKS

ENG 12/77 4474A

PART III - INVENTORY OF DAMS IN THE UNITED STATES
 SUPPLEMENTARY DATA

LOCATION	TOWN	NEED PERMIT NO.	STATE NUMBER	F.E.C. NO.	U.S.G.S. SHEET	DRAINAGE CHARACTERISTICS	FLOW DATA	CREST ABUT. ELEV. (FT)	RESERVOIR STORAGE AREA (ACRES)	FLASH BOARD FT	OUTLET CONDUITS	INVERT ELEV. (FT)	GENERATION UNITS	POWER DATA
1	WILSONVILLE		VT			NEBSTER MASS - DOWN	383	387	43	38				

VED 1 JAN 79 00(EST)