

CONNECTICUT WESTERN COASTAL AREA
WESTON , CONNECTICUT

SAMUEL P. SENIOR RESERVOIR DAM
CT 00108
and
POPPS MOUNTAIN DIKE
CT 00022

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM

The original hardcopy version of this report
contains color photographs and/or drawings.
For additional information on this report
please email



U.S. Army Corps of Engineers
New England District
Email: Library@nae02.usace.army.mil

DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
WALTHAM, MASS. 02154

SEPTEMBER 1978

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER CT 00108, CT 00022	2. GOVT ACCESSION NO. ADA14282	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Samuel P. Senior Reservoir Dam Popps Mountain Dike NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS		5. TYPE OF REPORT & PERIOD COVERED INSPECTION REPORT
		6. PERFORMING ORG. REPORT NUMBER
7. AUTHOR(s) U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION		8. CONTRACT OR GRANT NUMBER(s)
9. PERFORMING ORGANIZATION NAME AND ADDRESS		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
11. CONTROLLING OFFICE NAME AND ADDRESS DEPT. OF THE ARMY, CORPS OF ENGINEERS NEW ENGLAND DIVISION, NEDED 424 TRAPELO ROAD, WALTHAM, MA. 02254		12. REPORT DATE September 1978
		13. NUMBER OF PAGES 60
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMITED		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES Cover program reads: Phase I Inspection Report, National Dam Inspection Program; however, the official title of the program is: National Program for Inspection of Non-Federal Dams; use cover date for date of report.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) DAMS, INSPECTION, DAM SAFETY, Connecticut Western Coastal Area Weston, Conn. Samuel P. Senior Reservoir Dam Popps Mountain Dike		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) Samuel P. Senoir Dam is a linear concrete gravity structure, 990 ft. long, with a 300-ft. spillway located at the west end of the dam. The spillway is concaved looking downstream and consists of several steps on the downstream side. An earthen embankment section on the downstream side of the dam begins 61 ft. below the top of the dam and has slopes varying from 2:1 to 3:1. The dam is approx. 110 ft. long above the streambed. The dam is judged to be in good condition. The dike is judged to be in good condition. The overflow will be 2.7 ft. above the top of the dam.		

SAMUEL P. SENIOR DAM

CT 00108

AND

POPPS MOUNTAIN DIKE

CT 00022

CONNECTICUT WESTERN COASTAL AREA

WESTON, CONNECTICUT

PHASE I INSPECTION REPORT

NATIONAL DAM INSPECTION PROGRAM

PHASE I REPORT

NATIONAL DAM SAFETY PROGRAM

Name of Dam: SAMUEL P. SENIOR DAM

Name of Dike: POPPS MOUNTAIN DIKE

State Located: Connecticut

County Located: Fairfield County

Stream: Saugatuck River

Date of Inspection: 26 JULY 1978

BRIEF ASSESSMENT

Samuel P. Senior Dam is a linear concrete gravity structure, 990 feet long, with a 300-foot spillway located at the west end of the dam. The spillway is concaved looking downstream and consists of several steps on the downstream side. An earthen embankment section on the downstream side of the dam begins 61 feet below the top of dam and has slopes varying from 2:1 to 3:1. The dam is approximately 110 feet above the streambed. Approximately 2,000 feet northeast of the dam, a concrete gravity dike 670 feet long is provided. The structural height of the dike is 36 feet.


Based on the visual inspection of the site, review of available information and past performance of the dam, the dam is judged to be in good condition. There are surface patches of spalled concrete; however, no structural cracks were observed, nor was any visible evidence of abnormal settlements, heaving, deflections or lateral movements noted. The downstream berm is generally in good condition with no sloughing or wet spots noted. Based on the visual inspection of the site, review of available information and past performance of the dike, the dike is also judged to be in good condition. There are surface patches of spalled concrete; however, no structural cracks were observed, nor was any visible evidence of abnormal settlements, heaving, deflections or lateral movements noted.

The maximum spillway capacity at top of dam is 35 percent of the peak discharge rate of the test flood. Therefore, the test flood cannot be passed by the spillway without overtopping the dam. The overflow will be 2.7 feet above the top of the dam.

It is recommended that spalling at joints along the downstream face of the dam be repaired by the owner. Arrangements should be made to exercise the 48-inch blowoff periodically to ensure continued

serviceability. The owner should cut the trees and brush for a distance of 25 feet downstream of the dam and dike, ensuring that the tree roots are removed and the resulting holes are replaced with proper backfill. Because of the location of the dam, upstream of a populated area, round-the-clock surveillance should be provided during periods of high precipitation. The owner should develop a formal warning system and an operational procedure to follow in the event of an emergency.


Recommendations and remedial measures described should be implemented by the owner within 2 years after receipt of this Phase I Inspection Report.




S. Giavara, P.E.
Principal

Registered, CT 7634

This Phase I Inspection Report on Samuel P. Senior Reservoir Dam has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the Recommended Guidelines for Safety Inspection of Dams, and with good engineering judgment and practice, and is hereby submitted for approval.



CHARLES G. TIERSCH, Chairman
Chief, Foundation and Materials Branch
Engineering Division




FRED J. RAVENS, Jr., Member
Chief, Design Branch
Engineering Division



SAUL COOPER, Member
Chief, Water Control Branch
Engineering Division

APPROVAL RECOMMENDED:



JOE B. FRYAR
Chief, Engineering Division

PREFACE

This report is prepared under guidance contained in the recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D. C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily showing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

TABLE OF CONTENTS

<u>Section</u>	<u>Page</u>
Letter of Transmittal	
Brief Assessment	
Review Board Page	
Preface	i
Table of Contents	ii - iv
Overview Photo	v
Location Map	vi
1. PROJECT INFORMATION	
1.1 General	1
a. Authority	1
b. Purpose of Inspection	1
1.2 Description of Project	1
a. Description of Dam and Appurtenances	1
b. Location	2
c. Size Classification	2
d. Hazard Classification	2
e. Ownership	2
f. Purpose of Dam	2
g. Design and Construction History	2
h. Normal Operational Procedure	2
1.3 Pertinent Data	3
2. ENGINEERING DATA	
2.1 Design	5
2.2 Construction	5
2.3 Operation	7
2.4 Evaluation	7

<u>Section</u>	<u>Page</u>
3. VISUAL INSPECTION	
3.1 Findings	8
a. General	8
b. Dam	8
c. Appurtenant Structures	9
d. Reservoir Area	10
e. Downstream Channel	10
3.2 Evaluation	11
4. OPERATIONAL PROCEDURES	
4.1 Procedures	12
4.2 Maintenance of Dam	12
4.3 Maintenance of Operating Facilities	12
4.4 Description of any Warning System in Effect	12
4.5 Evaluation	12
5. HYDRAULIC/HYDROLOGIC	
5.1 Evaluation of Features	13
a. Design Data	13
b. Experience Data	14
c. Visual Observation	14
d. Overtopping Potential	14
6. STRUCTURAL STABILITY	
6.1 Evaluation of Structural Stability	15
a. Visual Observation	15
b. Design and Construction Data	15
c. Operating Records	15
d. Post-Construction Changes	15
e. Seismic Stability	15



<u>Section</u>	<u>Page</u>
7. ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES	
7.1 Dam Assessment	16
a. Condition	16
b. Adequacy of Information	16
c. Urgency	16
d. Need for Additional Investigation	16
7.2 Recommendations	16
7.3 Remedial Measures	16
a. Alternatives	16
b. Operation and Maintenance and Procedures	16

LIST OF APPENDICES

<u>Appendix</u>	<u>Description</u>
A	Visual Inspection - Check List
B	Engineering Data
C	Photographs
D	Hydrologic Computations
E	Information - National Inventory of Dams



SAMUEL P. SENIOR DAM



LOCATION MAP
SAUGATUCK RESERVOIR DAM
AND
POPPS MOUNTAIN DIKE
WESTON - EASTON , CONNECTICUT

PHASE I INSPECTION REPORT
SAMUEL P. SENIOR DAM CT 00108

SECTION 1 - PROJECT INFORMATION

1.1 GENERAL:

a. Authority. Public Law 92-367, August 8, 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a national program of dam inspection through the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region. Flaherty Giavara Associates, P.C. has been retained by the New England Division to inspect and report on selected dams in the State of Connecticut. Authorization and notice to proceed was issued to Flaherty Giavara Associates, P.C. under a letter of 25 April 1978 from Ralph T. Garver, Colonel, Corps of Engineers. Contract No. DACW33-78-0309 has been assigned by the Corps of Engineers for this work.

b. Purpose:

1) Perform technical inspection and evaluation of non-federal dams to identify conditions which threaten the public safety and thus permit correction in a timely manner by non-federal interests.

2) Encourage and assist the States to initiate quickly effective dam safety programs for non-federal dams.

3) To update, verify and complete the National Inventory of Dams.

1.2 DESCRIPTION OF PROJECT:

a. Description of Dam and Appurtenances. The Samuel P. Senior Dam, popularly known as the Saugatuck Reservoir Dam, is a linear concrete gravity structure, 990 feet long, with a 300-foot spillway located at the west end of the dam. The spillway is concaved looking downstream and consists of several steps on the downstream side whereupon the water is channeled into a 60-foot wide spillway channel until it discharges into the Saugatuck River some 400 feet downstream of the dam. An earthen embankment section on the downstream side of the dam begins at elevation 225, 61 feet below the top of dam, has a 16-foot wide top width and a 2:1 (horizontal) slope to elevation 200, then a 2-1/2:1 slope to elevation 190 and finally a 3:1 slope to elevation 182.

The top of the dam is about 11 feet wide, with a railing on both the upstream and downstream sides. The dam is approximately 110 feet above the streambed. An intake structure is located in the eastern portion of the dam, equipped with 6 48-inch influent sluice gates at various elevations. From the intake structure, a 36-inch pipe supplies water to the Bridgeport Hydraulic Company's facilities while a 48-inch lined tunnel can divert water to Hemlock Reservoir. Also, from the intake structure, a 48-inch blow off and 2 8-inch drains pass through the dam to a lower gate house and then terminate at a concrete endwall to discharge into the Saugatuck River. An additional 8-inch drain is provided between the lower gate house and this endwall. A linear concrete gravity dike 670 feet long north of the dam is also provided.

b. Location. The Samuel P. Senior Dam is located on the Saugatuck River, within the Connecticut Western Coastal Area in the Town of Weston. The dam is approximately 7 miles north of the Town of Westport. The concrete dike is about 2,000 feet north of the dam on the east side of reservoir in the Town of Easton.

c. Size Classification. The applicable guidelines indicate that for a large size classification the height of dam must be greater than or equal to 100 feet. The Samuel P. Senior Dam is 110 feet above the streambed. Therefore, the dam is classified as large. The applicable guidelines also indicate that for an intermediate category the storage (in acre-feet) for the impoundment must be greater than or equal to 1,000 and less than 50,000. The top of dike storage is 42,000 acre-feet and therefore the dike is classified as intermediate.

d. Hazard Classification. The dam is classified as having a high hazard potential. More than 100 houses are located in the area that could be affected by a dam failure flood wave. The same area would be affected by a dike failure flood wave.

e. Ownership. Samuel P. Senior Dam and Popp's Mountain Dike are owned by the Bridgeport Hydraulic Company, having its headquarters in Bridgeport, Connecticut.

f. Purpose of Dam. The dam was constructed to form an impounding reservoir. The reservoir forms part of the water company's supply and distribution system, providing potable water to the residents of the Greater Bridgeport area. Draw-off water can also be diverted to Hemlock Reservoir as needed.

g. Design and Construction History. The dam and dike were built around 1941. They were designed by Clarence M. Blair, Inc. of New Haven, Connecticut. The Bridgeport Hydraulic Company constructed the dam and dike with its own forces.

h. Normal Operating Procedures. Water is withdrawn at various depths from the intake structure and then conveyed to the distribution system through a 36-inch supply pipe. When needed, water can also be withdrawn and diverted to Hemlock Reservoir through a lined tunnel. An 8" drain pipe in the intake structure is used to maintain a continuous flow in the Saugatuck River.

1.3 PERTINENT DATA:

a. <u>Drainage Area</u> -	34.6 sq. miles
b. <u>Discharge at Dam Site</u> -	
Maximum Known Flood	Unknown
Warm Water Outlet	Not Available
Div. Tunnel Low Pool Outlet	Not Available
Diversion Tunnel Outlet	Not Available
Gated Spillway	None
Ungated Spillway at Max. Pool	11,900 CFS @ 1 Ft. freeboard
Total Spillway Cap. at Max. Pool	15,600 CFS @ no freeboard
c. <u>Elevation (above M.S.L.)</u> -	
Top of Dam	286
Max. Design Pool	Not Available
Full Flood Control Pool	Not Available
Recreation Pool	Not Available
Spillway Crest Ungated	280
Upstream Portal Invert. Div. Tunnel	Not Available
Downstream Portal Invert. Div. Tunnel	Not Available
Streambed at Centerline of Dam	170+
Maximum Tailwater	Unknown
d. <u>Reservoir</u> -	
Length of Max. Pool	18,500 feet
Length of Recreation Pool	Not Applicable
Length of Flood Control Pool	Not Applicable
e. <u>Storage</u> -	
Recreation Pool	Not Applicable
Flood Control Pool	Not Applicable
Design Surcharge	Not Applicable
Top of Dam	42,000 Acre-Feet
f. <u>Reservoir Surface (acres)</u> -	
Top of Dam	Not Available
Max. Pool	Not Available
Flood Control Pool	Not Applicable
Recreation Pool	Not Applicable
Spillway Crest	868

- g. Dam -
 Type: Linear concrete gravity
 Length: 990 feet
 Height: 130 feet
 Top Width: 11 feet
 Side Slopes: Downstream: 1 vertical to 0.7 horizontal
 Upstream: 1 vertical to 0.05 horizontal
 Impervious Core: Not Applicable
 Grout Curtain: Unknown
- h. Dike -
 Type: Linear concrete gravity
 Length: 665 feet
 Height: 36 feet.
 Top Width: 6'-8"
 Side Slopes: Downstream: 1 vertical to 0.65 horizontal
 Upstream: 1 vertical to 0.05 horizontal
 Zoning: Concrete
 Impervious Core: Not Applicable
 Grout Curtain: Unknown
- h. Diversion and Regulating Tunnel -
 Type: Lined tunnel
 Length: 1-1/2 miles
 Diameter: 48 inch
 Access: Intake Structure
 Regulation: Sluice Gate
- i. Spillway -
 Type: Ogee
 Length of Weir: 295 feet
 Crest Elevation: 280
 Gates: Ungated
 Upstream Channel: Reservoir
 Downstream Channel: Concrete
 Spillway is founded on: Bedrock
- j. Regulating Outlets -
 Gates: None
 Conduits: 36" diameter cast iron supply pipe
 48" diameter blow off pipe, cast iron

SECTION 2 - ENGINEERING DATA .

2.1 DESIGN:

The design of the dam and dike was made by Clarence M. Blair, Inc. of New Haven, Connecticut in 1939. Pertinent sections of the following information have been utilized in this report.

- a. Bridgeport Hydraulic Co. Saugatuck Development-General Plan at Dam - 1939.
- b. Bridgeport Hydraulic Co. Saugatuck Development - Contour Map of Dam Site - 1937.
- c. Bridgeport Hydraulic Co. Saugatuck Development - Cross Sections of Dam and Spillway - 1937.
- d. Bridgeport Hydraulic Co. Saugatuck Development - Plan of Gate House and Intakes - 1939.
- e. Bridgeport Hydraulic Co. Saugatuck Dam Site - Results of Borings - March 15, 1920.
- f. Bridgeport Hydraulic Co. - Core Drill Boring at Saugatuck River - undated.
- g. Bridgeport Hydraulic Co. - Section proposed for Saugatuck Dam - 1937.
- h. Bridgeport Hydraulic Co. Saugatuck Development - Plan of Dam at Notch - Popp's Mountain - 1940.

The "As-Built" drawings for this project are on file at the State Library in Hartford, Connecticut. The basis of design for the project is unknown.

2.2 CONSTRUCTION:

Some construction records are available at the offices of the Bridgeport Hydraulic Company and in files maintained by the State Supervisor of Dam Maintenance in Hartford, Connecticut and a formal review of these records has been made. From the inspection report submitted by the Resident Engineer dated February 5, 1942, the following information was obtained:

"In preparing the foundation, which was gneiss rock the overburden was first stripped and then the rock was excavated until a firm solid foundation was reached. The

depth of necessary excavation varied considerably over the length of the dam as shown by the profile. The greater part of the foundation sloped upward from the heel to the toe but where this condition did not exist the rock was drilled and blasted to present a very rough and uneven surface.

"Between the easterly end of the dam and the gate house, after excavation had been carried to an apparently sound foundation, twenty grout holes were drilled into which grout was forced under pressure. This work was done as an additional precaution to insure a sound foundation as more rock excavation had been necessary over this area to reach what seemed to be a good bottom."

"The aggregate for the concrete contained in the dam was obtained from a gravel deposit in the reservoir bottom, where a crushing, screening and washing plant was set up. The screened and washed material was hauled from this plant to the mixing plant in trucks. The sand used all passed a #4 square mesh and the stone was screened into three sizes, varying from 1/4" to 6". "

Two classes of concrete were mixed, one called Class A which was used on all exposed faces of the dam for a width of 5 to 7 feet and the other called Class B which was used on the interior of the dam. "Cylinders 6" x 12" were made each day from concrete taken from the forms [tested by the Pittsburgh Testing Laboratory], which gave average strength of 2000# per square inch in 7 days and 4200# in twenty-eight days for Class A concrete and 1800# in seven days and 3700# in twenty-eight days for Class B concrete."

"The dam was built in sections forty feet long except at the ends where the lengths were 45 feet and 48 feet. The gate house section, 69 feet in length, was constructed in two equal halves. For water stops in the joints, keys 12" x 24" spaced 10 feet apart were set at the ends of each section. Concrete was deposited in forms 4'-2" high and each lift of this height was placed in three courses. Before concrete was placed on any rock surface or on any concrete already in place all dirt, laitance and other foreign matter was removed by thoroughly washing and cleaning the surface." Extraordinary attention was paid to this cleaning because it was considered most important. The spillway was constructed in the same general way as the dam.

"An earth embankment was placed against the downstream face of the dam to elevation 235. This was composed of material excavated from the dam foundation and from the spillway channel and consisted mostly of rock. Special care was taken to have coarse material against the dam itself in order to provide proper drainage."

The foundation for the Dike was prepared in the same manner as that of the dam and the concrete consisted of the same materials. Expansion joints with keys were provided at forty foot intervals and the concrete was placed in the forms in 1-1/2 yard batches after having been mixed at the same mixing plant utilized for the dam.

Construction of the dam was carried out by Bridgeport Hydraulic Company forces.

2.3 OPERATION:

No formal operation records are available.

2.4 EVALUATION:

a. Availability. Available data was reviewed by members of the inspection team and office personnel and found to be generally accurate and complete.

b. Adequacy. The data available is adequate for the purposes of a Phase I investigation.

c. Validity. There is no reason to question the validity of the available data.

SECTION 3 - VISUAL INSPECTION

3.1 FINDINGS:

a. General. The structure appears to be in good condition, except for surface patches of spalled concrete. No structural cracks were observed, nor was any visible evidence of abnormal settlements, heaving, deflections or lateral movements noted. The downstream berm is generally in good condition with no sloughing or wet spots noted. The berm appeared to be relatively shallow in the vicinity of the right and left abutments.

Overall the spillway appeared to be in good condition; a crack was noted at the crest of the spillway where it meets the training wall.

b. Dam.

1) Upstream Face - At or above the water line, slight spalling was evident. Generally the concrete was in good condition.

2) Downstream Face - There was evidence of wet spots, staining, efflorescence and joint spalling at nearly every construction joint. From Station 1+90 to Station 2+30 about 30 feet above the berm there was a horizontal line of efflorescence at a horizontal pour joint. In the panel between Station 3+45 to 3+85, about 10 feet up from the top of the berm, there are four drilled holes about 2 inches in diameter, depth undetermined, spaced 3 to 4 feet apart horizontally, which were dry but showed evidence of efflorescence (the purpose of these holes is unknown). There was quite a bit of spalling below the holes and some slight spalling above them. The joint at Station 3+85 was wet and stained from about the berm to a height of 35 feet. For about 20 feet from the top of berm, the joint was badly spalled and quite deteriorated.

3) Spillway - The concrete in the spillway and steps was found to be in generally good condition. A crack was noted at the crest of the spillway, where it meets the training wall. Some surface spalling of the concrete steps was observed.

4) Earth Embankment - The downstream embankment is generally in good condition with no sloughing or wet spots noted. The berm is 15 feet wide at the top of the slope and slopes toward the concrete dam. There is a depression at each joint of the dam. The depressions are filled with stone. The berm appeared to be relatively shallow in the vicinity of the right and left abutments.

Approximately 150 feet downstream of the toe of the downstream berm is an extensive area of dumped riprap adjacent to the blow-off outlet works. The riprap has been covered with a thin veneer of soil which has been eroded away in several locations.

Several large depressions, approximately 3' x 4', exist in the flat grassed area downstream from the earth berm approximately 125 feet in the vicinity of Station 3+0 and 3+50. The depressions vary in depth between 6" to 15". Another depression, 2' x 2' x 1' deep, was located approximately 50 feet down on the berm slope in the vicinity of Station 2+29. The origin of these depressions is not known.

No animal burrows were encountered on the slopes of the downstream embankment.

c. Appurtenant Structures.

1) Spillway Channel - The spillway channel is in good condition. Low concrete walls on the right and left side of the channel are also in good condition. Layered mica gneiss bedrock is exposed in the bottom of the spillway channel from the spillway weir to the large pool at the end of the left concrete training wall. A small amount of seepage was noted in the channel floor. A rock fall has occurred in the upper part of the channel from its east bank, however, it does not restrict flow. The blow-off discharge structure is in excellent condition.

2) Upper Gate House - This structure, located on upstream face of dam, was clean and neat. Gates are reportedly operated once a year, and were inspected by divers in 1977 with minor repair work required at stem guides. There are cracks in the brickwork in the northwest, west, and southwest walls. The cracks are wide enough to allow daylight through in some places. The building has 100 amp, 240 volt electrical service for lights and a deicer which is located adjacent to the spillway.

3) Lower Gate House - This structure, on the downstream side of the dam, is in good condition, but is subject to condensation and high humidity due to the cold water flowing in the pipes through the structure. It has 30 amp, 120 volt electrical service for lights, flow meters, and a furnace.

4) Concrete Gravity Dike (Popps Mountain) - Generally the dike is in good condition. Along the full length of the upstream face about 2 feet above the water line, scouring of the concrete has occurred.

At the top of the dike, at Station 1+80, there is a crack the full width of the dam and the lip or coping has deteriorated.

At Station 4+20 there is a crack adjacent to the joint for the full width, and at the upstream edge, the lip has spalled off.

At Station 4+63 at the top, a one foot wide strip several inches deep for the full width has deteriorated and spalled off, and the lip at the upstream face has also spalled off.

At Station 5+40, there is a crack adjacent to the joint the full width of the dike and on the downstream face, the lip has spalled off.

On the downstream face of the dike, at Station 1+80, from the top to about 4 feet down from the top there is a piece of concrete about one foot in width and several inches deep breaking away from the face.

Considerable tree growth and bushes exist in the filled area along the toe of the dike.

No evidence of seepage or wet areas were found along the toe of the dam from the right to left abutments. At approximately Station 1+25, a wet area exists approximately 100 feet east of the dam in a naturally occurring gully. There is a small amount of iron-stained seepage flowing north from this area. It is not evident whether the flow is from underneath the dam or naturally occurring drainage from the adjacent steep watershed area.

d. Reservoir Area. The reservoir perimeter has well vegetated banks at moderate to steep slopes. There was no evidence of slides or sloughing. No noticeable debris or obstructions were seen in the vicinity of the intake tower. The depth of sediment, and rate of accumulation in the reservoir, is unknown.

e. Downstream Channel. The open channel extending downstream from the junction of the 48" blow-off and spillway channels is in excellent condition. It has a bed of coarse gravel and cobbles, and there is no evidence of aggradation or recent degradation. The banks are partly lined with riprap, and are stable. Seepage was observed entering this channel between the spillway and blow-off channels. This clear water is apparently seeping from a bank of fill material overlying the original stream channel.

3.2 EVALUATION:

a. Dam. Visual observation revealed that the dam and attendant structures are structurally sound and that no immediate actions to remedy any serious problems should be taken. There was no visual indication of dam weakness.

b. Dike. Visual observations indicated that the dike was in good condition. Although spalling has occurred at several joints, this does not affect the stability of the dike.

SECTION 4 - OPERATIONAL PROCEDURES

4.1 PROCEDURES:

The dam 8" blow-off drain line is operated to maintain minimum flow of the Saugatuck River. The reservoir is used as a storage reservoir and is connected into the upper end of Hemlocks Reservoir through a tunnel about 1-1/2 miles long. Take off points from the reservoir are changed periodically.

4.2 MAINTENANCE OF DAM:

The dam, dike and associated structures are well maintained with a regular program of grass mowing and general maintenance in effect. Yearly routine inspections are carried out by Bridgeport Hydraulic Company staff. A consultant was hired to perform a cursory inspection of Bridgeport Hydraulic Company dams during November 1976.

4.3 MAINTENANCE OF OPERATING FACILITIES:

The operating valves were inspected recently; although the results of the inspection are not available, generally the valves/valve stems need some repair.

4.4 DESCRIPTION OF ANY WARNING SYSTEM IN EFFECT:

There was no warning system of any kind in effect at the time of the inspection.

4.5 EVALUATION:

The Samuel P. Senior Dam and dike, which are almost 40 years old, are well operated and maintained. Although not designed for rapid drawdown, it should be noted that, if the need should arise, drawdown could be effected by the following procedures:

a. Allowing for maximum discharge through the 48" blow-off and 8" drain line.

b. Allowing for maximum discharge through the 6' - 4" inside horseshoe shaped concrete tunnel to Hemlocks Reservoir.

The blow-off was not operated during the site inspection, therefore comments on the serviceability cannot be made. The valve should be tested on a periodic basis to insure that it could be operated if required.

SECTION 5 - HYDRAULICS/HYDROLOGY

5.1 EVALUATION OF FEATURES:

a. Design Data. There is no available information on the hydraulic design criteria for this dam and appurtenances. Under established criteria (OCE Guidelines) the recommended spillway design flood for size (large) and hazard potential (high) classification is the probable maximum flood (PMF). The PMF is the flood that may be expected from the most severe combination of critical meteorologic and hydrologic conditions that are reasonably possible in the region.

An estimate of the magnitude of the PMF at the site is based on an analysis of several sets of regional flood frequency data as presented in Appendix II.

As a conservative approach to the investigation, the more critical design PMF hydrograph was used throughout. The peak inflow rate of the PMF of 48,800 CFS was used as the test flood.

A stage-discharge relationship was calculated for the spillway and indicates the following flows, based upon a coefficient of 3.6 and an effective length of 295 feet.

Stage - Discharge Relationship

<u>Stage</u>	<u>Head, Ft.</u>	<u>Discharge Rate, CFS</u>
280	0	0
281	1	1,060
282	2	3,000
283	3	5,520
284	4	8,500
285	5	11,870
286	6	15,610

The maximum spillway capacity, with no freeboard, is equal to about 35 per cent of the peak discharge rate of the test flood. In order to determine the effect of the reservoir storage capacity, a hydrograph of the test flood was routed through the reservoir.

The hydrograph was formed by assuming the test flood had a duration of 24 hours, with the peak of 48,800 CFS occurring at 8 hours from the beginning of runoff. The rising and falling limbs of the hydrograph were assumed to be changing at a constant rate, forming a triangle. The routing operation indicated that the peak rate of discharge would be reduced to 46,000 CFS, resulting in a stage elevation of 288.7 feet.

b. Experience Data. During the flood of October 15 - 17, 1955, the dam was not overtopped. United States Geologic Survey information indicates that the flow of October 16, 1955 had a peak rate of 7,100 CFS, which is the maximum flood of record for the Saugatuck River.

c. Visual Observations. The on-site inspection of the dam provided the data for the hydraulic evaluation of the spillway.

d. Overtopping Potential. The elevation-discharge relations indicate that the test flood would not be passed by the spillway without overtopping the dam. The spillway capacity is about 35 per cent of the test flood, and the stage would be 2.7 feet above the top of the dam and dike.

SECTION 6 - STRUCTURAL STABILITY

6.1 EVALUATIONS OF STRUCTURAL STABILITY:

- a. Visual Observations. No evidence was observed that would indicate structural instability of the dam and dike.
- b. Design and Construction Data. The design and construction data available are not sufficient to formally evaluate the stability of the dam and dike.
- c. Operating Records. There are no available records which indicate evidence of stability problems since the dam and dike were constructed in the early 1940's. As the Samuel P. Senior dam has been designed and constructed as a water supply dam and has been subjected to a full head of water a majority of the time since construction, its stability could be considered to be adequate based on past performance.
- d. Post-Construction Changes. The bridge that provided access to the dam site, across the spillway section, has been removed.
- e. Seismic Stability. This dam is in Seismic Zone 1 and, in accordance with recommended Phase I guidelines, does not warrant seismic analysis.

SECTION 7 - ASSESSMENT, RECOMMENDATIONS AND
REMEDIAL MEASURES

7.1 DAM ASSESSMENT:

a. Condition. Based on the visual inspection, records available and past operational performance, the dam is judged to be in good condition.

The project will not pass the test flood without overtopping the dam, and therefore the spillway capacity is inadequate. The spillway capacity is judged seriously inadequate, as the project will not pass one-half the test flood without overtopping the dam.

b. Adequacy of Information. The information available is such that the assessment of the safety of the dam must be based primarily on the visual inspection and past operational performance of the structure.

c. Urgency. The recommendations and remedial measures should be implemented by the owner within 2 years after receipt of this report.

d. Need for Additional Investigation. Additional investigations to further assess the adequacy of the dam do not appear necessary. However, it appears that detailed investigations should be initiated by the owner to determine requirements for obtaining additional spillway capacity.

7.2 RECOMMENDATIONS:

It is recommended that the following measures be undertaken by the owner:

1) Spalling at joints along the downstream face should be repaired.

7.3 REMEDIAL MEASURES:

Although the dam is generally maintained in good condition, it is considered important that the following items be accomplished:

a. Alternatives. Not applicable.

b. Operation and Maintenance and Procedures.

1) Arrangements should be made to exercise the 48" blow-off periodically to ensure continued serviceability.

2) The owner should cut the trees and brush for a distance of 25 feet downstream of the dam and dike, ensuring that the tree roots are removed and the resulting holes are replaced with proper backfill.

3) Because of the location of the dam, upstream of a populated area, round the clock surveillance should be provided during periods of high precipitation.

4) The owner should develop a formal warning system. An operational procedure to follow in the event of an emergency should also be adopted.

5) The owner should provide continued periodic inspections at a two year frequency.

APPENDIX A

VISUAL INSPECTION - CHECK LIST

PERIODIC INSPECTION CHECK LIST

AT Samuel P. Senior Dam

DATE July 26, 1978

TOR Anthony D. Rummo

DISCIPLINE Structural

TOR Robert C. Smith

DISCIPLINE Project Manager

AREA EVALUATED	CONDITION
<u>THE DAM STRUCTURE</u>	
Overall Condition Concrete Surfaces	The condition of concrete is good.
Movement or Settlement of Crest	No noticeable movement of dam crest or side slopes.
Vertical Alignment	Good horizontal and vertical alignment.
Horizontal Alignment	
Condition at Abutment and Other Structures	
Structural Cracking	None
Spalling	Slight surface spalling D/S face.
Visible Reinforcing	
Discoloring or Staining of Concrete	Slight staining of several joints.
Condition of Monolith/Construction Joints	Good
Leakage - Foundation, Abutment, Faces	None observed.
Seepage or Efflorescence	Some efflorescence observed.
Foundation Damage, Undermining	None observed.
Spillway Passages	Spillway in good condition, minor spalling.
Inlets	

PERIODIC INSPECTION CHECK LIST

Samuel P. Senior Dam

DATE July 26, 1978

OR Richard F. Murdock

DISCIPLINE Geotechnical

OR Robert C. Smith

DISCIPLINE Project Manager

AREA EVALUATED	CONDITION
<u>EMBANKMENT</u>	
Elevation	286
Pool Elevation	279
Time Impoundment to Date	
Ice Cracks	
Present Condition	
Settlement or Settlement of Upstream	
Vertical Movement	None
Local Alignment	Good
Horizontal Alignment	Good
Distortion at Abutment and at Concrete Structures	Good
Observations of Movement of Structural Items on Slopes	None
Sliding on Slopes	
Sloughing or Erosion of Slopes or Abutments	Some minor surface erosion on west slope of dam.
Slope Protection - Preparation Failures	None
Vertical Movement or Cracking Upstream or near Toes	None
Vertical Embankment or Down- stream Seepage	None

PERIODIC INSPECTION CHECK LIST

Samuel P. Senior Dam DATE July 26, 1978
 OR Richard F. Murdock DISCIPLINE Geotechnical
 OR Robert C. Smith DISCIPLINE Project Manager

AREA EVALUATED	CONDITION
<u>EMBANKMENT</u> - (continued)	
g or Boils	None
ation Drainage Features	None
rains	None
umentation System	None

PERIODIC INSPECTION CHECK LIST

Popps Mountain Dike DATE July 26, 1978
 OR Richard F. Murdock DISCIPLINE Geotechnical
 OR Robert C. Smith DISCIPLINE Project Manager

AREA EVALUATED	CONDITION
<u>EMBANKMENT</u>	
: Elevation	286
ent Pool Elevation	279
um Impoundment to Date	
ace Cracks	
nent Condition	
nent or Settlement of est	
ral Movement	
ical Alignment	
zontal Alignment	
ition at Abutment and at ncrete Structures	
ations of Movement of ructural Items on Slopes	None
passing on Slopes	
ghing or Erosion of opes or Abutments	None
Slope Protection - rap Failures	None
ual Movement or Cracking or near Toes	None
ual Embankment or Down- ream Seepage	Seepage observed at Station 1+0, approximately 100 ft. downstream of dam.

PERIODIC INSPECTION CHECK LIST

Popps Mountain Dike DATE July 26, 1978
 OR Richard F. Murdock DISCIPLINE Geotechnical
 OR Robert C. Smith DISCIPLINE Project Manager

AREA EVALUATED	CONDITION
<u>EMBANKMENT</u> - (continued)	
g or Boils	None
ation Drainage Features	None
rains	None
umentation System	None

PERIODIC INSPECTION CHECK LIST

CT Popps Mountain Dike

DATE July 26, 1978

CTOR Anthony D. Rummo

DISCIPLINE Structural

CTOR Robert C. Smith

DISCIPLINE Project Manager

AREA EVALUATED	CONDITION
<u>ETE DAM STRUCTURE</u>	
eral Condition Concrete surfaces	The concrete in dike is in good condition.
ement or Settlement of rest	None observed.
tical Alignment	Good alignment.
izontal Alignment	
dition at Abutment and ther Structures	Excellent
uctural Cracking	None
lling	Some surface spalling observed at top of dike.
ible Reinforcing	
ting or Staining of oncrete	None
dition of Monolith/ onstruction Joints	Good
ins - Foundation, oint, Faces	
Seepage or Efflorescence	Very slight
undation Damage, Undermining	None
er Passages	None
tments	

PERIODIC INSPECTION CHECK LIST

T Samuel P. Senior Dam

DATE July 26, 1978

TOR James MacBroom

DISCIPLINE Hydraulics/Hydrology

TOR _____

DISCIPLINE _____

AREA EVALUATED	CONDITION
<p><u>WORKS - INTAKE CHANNEL AND KE STRUCTURE</u></p> <p>approach Channel</p> <p>Slope Conditions</p> <p>Bottom Conditions</p> <p>Rock Slides or Falls</p> <p>Log Boom</p> <p>Debris</p> <p>Condition of Concrete Lining</p> <p>Drains or Weep Holes</p> <p>Intake Structure</p> <p>Condition of Concrete</p> <p>Stop Logs and Slots</p>	<p>Good condition, slight spalling at water line.</p> <p>Good condition.</p>

PERIODIC INSPECTION CHECK LIST

T Samuel P. Senior Dam

DATE July 26, 1978

TOR James MacBroom

DISCIPLINE Hydraulics/Hydrology

TOR _____

DISCIPLINE _____

AREA EVALUATED	CONDITION
<p><u>WORKS - CONTROL TOWER</u></p> <p>Concrete and Structural</p> <p>General Condition</p> <p>Condition of Joints</p> <p>Spalling</p> <p>Visible Reinforcing</p> <p>Rusting or Staining of Concrete</p> <p>Any Seepage or Efflorescence</p> <p>Joint Alignment</p> <p>Unusual Seepage or Leaks in Gate Chamber</p> <p>Cracks</p> <p>Rusting or Corrosion of Steel</p> <p>Mechanical and Electrical</p> <p>Air Vents</p> <p>Float Wells</p> <p>Crane Hoist</p> <p>Elevator</p> <p>Hydraulic System</p>	

PERIODIC INSPECTION CHECK LIST

CT Samuel P. Senior Dam

DATE July 26, 1978

CTOR James MacBroom

DISCIPLINE Hydraulics/Hydrology

CTOR _____

DISCIPLINE _____

AREA EVALUATED	CONDITION
<u>T WORKS - CONTROL TOWER</u> (continued)	
Service Gates	Good condition
Emergency Gates	Unknown
Lightning Protection System	Good condition
Emergency Power System	
Wiring and Lighting System In Gate Chamber	

PERIODIC INSPECTION CHECK LIST

CT Samuel P. Senior Dam,

DATE July 26, 1978

CTOR Richard F. Murdock

DISCIPLINE Geotechnical

CTOR James MacBroom

DISCIPLINE Hydraulics/Hydrology

AREA EVALUATED	CONDITION
<u>F WORKS - SPILLWAY WEIR, ROACH AND DISCHARGE CHANNELS</u>	
Approach Channel	Underwater (Reservoir)
General Condition	
Loose Rock Overhanging Channel	
Trees Overhanging Channel	
Floor of Approach Channel	
Weir and Training Walls	
General Condition of Concrete	Good condition
Rust or Staining	None
Spalling	
Any Visible Reinforcing	None
Any Seepage or Efflorescence	None
Drain Holes	Some drainage of drain holes.
Discharge Channel	
General Condition	
Loose Rock Overhanging Channel	
Trees Overhanging Channel	A few large healthy trees present.
Floor of Channel	Good - bedrock surfaces.
Other Obstructions	None

PERIODIC INSPECTION CHECK LIST

AT Samuel P. Senior Dam

DATE July 26, 1978

CTOR James MacBroom

DISCIPLINE Hydraulics/Hydrology

CTOR _____

DISCIPLINE _____

AREA EVALUATED	CONDITION
<p><u>WORKS - OUTLET STRUCTURE</u> <u>OUTLET CHANNEL</u></p> <p>eral Condition of Concrete</p> <p>or Staining</p> <p>lling</p> <p>sion or Cavitation</p> <p>ible Reinforcing</p> <p>Seepage or Efflorescence</p> <p>lition at Joints</p> <p>in Holes</p> <p>nel</p> <p>oose Rock or Trees Over- hanging Channel</p> <p>ondition of Discharge Channel</p>	<p>No trees or loose rock over- hanging channel.</p> <p>The channel is in excellent condition.</p>

APPENDIX B
ENGINEERING DATA

ENGINEERING DATA
 DESIGN, CONSTRUCTION, OPERATION
 PHASE I



I.D. NO. CT 00108

ITEM	REMARKS
AS-BUILT DRAWINGS	Conn. State Library - Hartford
REGIONAL VICINITY MAP	Available From U.S.G.S.
CONSTRUCTION HISTORY	Records State D.E.P. and Bridgeport Hydraulic Co.
TYPICAL SECTIONS OF DAM	Available From Plans.
OUTLETS - Plan	From Plans
- Details	From Plans
- Constraints	Unknown
- Discharge Ratings	Unavailable
RAINFALL/RESERVOIR RECORDS	From Bridgeport Hydraulic Co.
DESIGN REPORTS	None
GEOLOGY REPORTS	None
DESIGN COMPUTATIONS	None
HYDROLOGY & HYDRAULICS	None
DAM STABILITY	Available From Plan
SEEPAGE STUDIES	None
MATERIALS INVESTIGATIONS	None
BORINGS RECORDS	From Plan
LABORATORY	None
FIELD	None

DESIGN, CONSTRUCTION, OPERATION
PHASE I

I.D. NO. CT 00100


ITEM	REMARKS
POST-CONSTRUCTION SURVEYS OF DAM	None
BORROW SOURCES	Construction Records
MONITORING SYSTEMS	None
MODIFICATIONS	Unknown
HIGH POOL RECORDS	Approximate From Bridgeport Hydraulic Co. Records
POST-CONSTRUCTION ENGINEERING STUDIES AND REPORTS	None
PRIOR ACCIDENTS OR FAILURE OF DAM DESCRIPTION REPORTS	None
MAINTENANCE OPERATION RECORDS	Inspection Reports From Bridgeport Hydraulic Co.
SPILLWAY PLAN	
SECTIONS	Plans
DETAILS	Plans
OPERATING EQUIPMENT PLANS & DETAILS	Plans



DOWNSTREAM ELEVATION OF DAM


NTS

SAMUEL P. SENIOR DAM
SAUGATUCK RIVER



CROSS SECTION OF DAM
NTS

SAMUEL P. SENIOR DAM
SAUGATUCK RIVER




BRIDGEPORT HYDRAULIC Co.
 SAUGATUCK, DEVELOPMENT
 GENERAL PLAN AT DAM
 TOWN OF WESTON, CONN.

March, 1911

Revised to Feb. 1, 1910
 Apr. 16, 1910

CLARENCE M. BLAIR ENGINEERS & ARCHITECTS NEW HAVEN, CONN.
Prepared by: J. W. R. R. Drawn by: J. W. R. R. Date: March, 1911




DGEPORT HYDRAULIC CO.
 SAUGATUCK DEVELOPMENT
 TOUR MAP OF DAM SITE
 TOWN OF WESTON, CONN.

Note: @ denotes boring; G - elevation of ground; R - elevation of rock


June, 1937

Revised to Jan. 1, 1938
 Apr. 21, 1934
 May 24, 1936
 Apr. 22, 1937


Sheet No.	1 of 1
Date	June 1, 1937
Scale	1" = 100'




SECTION A-A




SECTION B-B




SECTION E-E



SECTION C-C




SECTION D-D




CROSS SECTION OF DAM

N.T. INC.
 J. VEIGAS
 OHR
 1st RR
 2nd RR
 3rd RR


BRIDGEPORT HYDRAULIC CO.
 SAUGATUCK DEVELOPMENT
 CROSS SECTIONS OF DAM AND SPILLWAY
 TOWN OF WESTON, CONN.
 Scale 1"=1'
 August, 1937
 Prepared by H. M. H. H.
 Nov. 7, 1937




ELEVATION LOOKING EAST




SECTIONAL ELEVATION LOOKING UPSTREAM




ELEVATION LOOKING WEST




FLOOR PLAN




SECTIONAL PLAN SHOWING WELLS



SECTION A-A



SECTION B-B




SECTION C-C

BRIDGEPORT HYDRAULIC CO.
 SAUGATUCK DEVELOPMENT
 PLAN OF GATE HOUSE AND INTAKES
 TOWN OF WESTON, CONN.

Scale 1/4" = 1'

Printed 14 March 1908

October, 1897




Boring	Elev. Surface of Ground	Elev. Top of Rock	Elev. Bottom of Boring	Remarks
1	252.6	246.4	218.5	
2	219.0	218.0	188.0	Lost water in seam El. 200, not regained
3	230.5	227.6	200.4	Lost water at Elev. 215 regained it at Elev. 214
4	188.0	177.0	147.0	
5	159.5	158.0	121.0	Soft rock from Elev. 158 to Elev. 148
6	163.0	160.4	130.4	
7	213.6	211.2	189.4	Seamy from Elev. 211 to Elev. 199
8	229.0	216.0	186.0	Lost water Elev. 212
9	251.6	230.5	208.5	Lost water Elev. 228
10	275.0	269.4	239.6	Lost water Elev. 260

BRIDGEPORT HYDRAULIC CO.
 SAUGATUCK DAM SITE
 TOWN OF WESTON, CONN.
 SCALE 1"=100' MARCH 15, 1920.

BRIDGEPORT HYDRAULIC CO.
SECTION PROPOSED FOR SAUGATUCK DAM
TOWN OF WESTON, CONN.


Scale $\frac{1}{2}''=1'$

March, 1937




BLAIR & MARCHANT, INC.
CIVIL ENGINEERS & SURVEYORS,
NEW HAVEN, CONN.

Checked by	Traced by
Approved	Checked by
March 1937	File




Note: Profile taken on Revised Base Line


PROFILE OF DAM
Scales: Hor. 1"=40'
Vert. 1"=10'



STATION	ELEV.	WIDTH OF DAM	WIDTH OF SECTION	VOLUME	AREA	PERCENTAGE	PERCENTAGE
1	168.0	10.0	10.0	0.000	10.0	100.0	100.0
2	167.0	10.0	10.0	0.000	10.0	100.0	100.0
3	166.0	10.0	10.0	0.000	10.0	100.0	100.0
4	165.0	10.0	10.0	0.000	10.0	100.0	100.0
5	164.0	10.0	10.0	0.000	10.0	100.0	100.0
6	163.0	10.0	10.0	0.000	10.0	100.0	100.0
7	162.0	10.0	10.0	0.000	10.0	100.0	100.0
8	161.0	10.0	10.0	0.000	10.0	100.0	100.0
9	160.0	10.0	10.0	0.000	10.0	100.0	100.0
10	159.0	10.0	10.0	0.000	10.0	100.0	100.0
11	158.0	10.0	10.0	0.000	10.0	100.0	100.0
12	157.0	10.0	10.0	0.000	10.0	100.0	100.0
13	156.0	10.0	10.0	0.000	10.0	100.0	100.0
14	155.0	10.0	10.0	0.000	10.0	100.0	100.0
15	154.0	10.0	10.0	0.000	10.0	100.0	100.0
16	153.0	10.0	10.0	0.000	10.0	100.0	100.0
17	152.0	10.0	10.0	0.000	10.0	100.0	100.0
18	151.0	10.0	10.0	0.000	10.0	100.0	100.0
19	150.0	10.0	10.0	0.000	10.0	100.0	100.0
20	149.0	10.0	10.0	0.000	10.0	100.0	100.0
21	148.0	10.0	10.0	0.000	10.0	100.0	100.0
22	147.0	10.0	10.0	0.000	10.0	100.0	100.0
23	146.0	10.0	10.0	0.000	10.0	100.0	100.0
24	145.0	10.0	10.0	0.000	10.0	100.0	100.0
25	144.0	10.0	10.0	0.000	10.0	100.0	100.0



CONTOUR MAP OF DAM SITE
Scale 1"=40'



CROSS SECTION OF DAM
Scale 1/2"=1'


BRIDGEPORT HYDRAULIC CO.
SAUGATUCK DEVELOPMENT
PLAN OF DAM AT NOTCH - POPPS MOUNTAIN
TOWN OF WESTON, CONN.

Scales indicated

January, 1940

LAIR, Inc.
RVEYOPS
CONN.
WESTON
JAN 1940

APPENDIX C
PHOTOGRAPHS



SAMUEL P. SENIOR DAM
LOCATION OF PHOTOGRAPHS



PHOTO #1: View of the western, downstream face of the dam.



PHOTO #2: View along the face of the dam, looking east.



PHOTO #3: Looking west along the crest of the dam.



PHOTO #4: Upstream face of the dam and upper gate house.



PHOTO #5: View of the spillway, looking west.



PHOTO #6: View of the spillway and dam, looking east from west abutment.



PHOTO #7: The spillway discharge channel, looking down at the natural river in the background.



PHOTO #8: Blow-off discharge point, showing the wingwalls and riprap.



PHOTO #9: Typical spalling at a construction joint.



PHOTO #10: Holes cored in concrete dam—purpose unknown.



PHOTO #11: View looking south along the concrete dike.




PHOTO #12: View looking north along the concrete dike.



PHOTO #13: Downstream face of the concrete dike.

APPENDIX D

HYDROLOGIC COMPUTATIONS



DRAINAGE AREA MAP
SAMUEL P. SENIOR DAM
WESTON , CONNECTICUT



P.M.F. PEAK FLOW ESTIMATE

DRAINAGE AREA IS 34.6 SQ. MILES

METHOD #1

REFER TO "PRELIMINARY GUIDANCE FOR ESTIMATING PMF DISCHARGES" by NEW ENGLAND DIVISION, CORPS OF ENGINEERS

UNIT FLOW = 1410 CFS / mi² (ROLLING CURVE)
PMF ≈ (34.6 SQ mi) × (1410 CFS/mi²) = 48,786 CFS

METHOD #2

REFER TO "CONN WATER RESOURCE BULLETIN NO. 17, PART 4", BY U.S.G.S.

MEAN ANNUAL FLOOD = 1200 CFS
Q₁₀₀ = 5 × MAF = 5 × 1200 CFS = 6000 CFS

PMF ≈ 5 × Q₁₀₀ (APPROXIMATE)
PMF ≈ 5 × 6000 CFS = 30,000 CFS

METHOD #3

REFER TO FAIRFIELD, CT F.I.A. FLOOD INSURANCE STUDY, "FREQUENCY, DISCHARGE, DRAINAGE AREA CURVES"

Q₁₀₀ = 7000 CFS
PMF ≈ 5 × Q₁₀₀ (APPROXIMATE)
PMF ≈ 5 × 7000 CFS = 35,000 CFS

USE 48,800 CFS FOR SPILLWAY TEST FLOOD



FORMATION OF INFLOW HYDROGRAPH

- 1) P.M.F. \approx 48,800 CFS
- 2) FORM A TRIANGULAR HYDROGRAPH WITH A 24 HOUR DURATION, PEAK @ 8 HOURS

<u>TIME HOURS</u>	<u>UNIT FLOW RATE</u>	<u>FLOW RATE CFS</u>
0	0.00	0
2	0.25	12,200
4	0.50	24,400
6	0.75	36,600
8	1.00	48,800
10	0.875	42,700
12	0.75	36,600
16	0.50	24,400
20	0.25	12,200
24	0.00	0

6-10
K DAM



FLAHERTY-GIAVARA ASSOCIATES
ENVIRONMENTAL DESIGN CONSULTANTS
ONE COLUMBUS PLAZA, NEW HAVEN, CONN. 06510/203/789-1260

SHEET NO. 3 OF 3
BY JGM DATE 8/7/78
CHK'D. BY EJK DATE 8/23/78

SPILLWAY CAPACITY

$$Q = C L H^{3/2}$$

$$C \approx 3.6$$

$$L = 295 \text{ FT (EFFECTIVE LENGTH)}$$

$$H = 6 \text{ FT (EL. 286 - EL. 280)}$$

$$Q_{\text{max}} = 3.6 (295) (6)^{1.5} = 15,608 \text{ CFS}$$

$$\frac{\text{SPILLWAY CAPACITY}}{\text{TEST FLOOD}} = \frac{15,608}{48,800} = 32 \%$$

SAUGATUCK DAM

78-36-10

FLOOD ROUTING

JGM

9/19/78

INPUT DATA:

SEGMENT 1
SEGMENT 2
IE=280

UNSUBMERGED WEIR

DISCHARGE COEFFICIENT = 3.6
DISCHARGE COEFFICIENT = 3
O.0 E=280 A=868.00

LENGTH OF WEIR = 295
LENGTH OF WEIR = 1360
E=290 A=868.00

ELEVATION OF WEIR = 280
ELEVATION OF WEIR = 286

HOUR	INFLOW	MASS INFLOW	WATER EL.	TAIL WATER	OUTFLOW	MASS OUTFLOW	STORAGE(R)	STORAGE(A)
0.00	0CFS	0.00AC-F	280.00FT	0.00FT	0CFS	0.00AC-F	0.00AC-F	0.00AC-F
2.00	12,200CFS	1,008.26AC-F	281.05FT	0.00FT	1,146CFS	94.76AC-F	913.50AC-F	913.50AC-F
4.00	24,400CFS	4,033.05AC-F	283.70FT	0.00FT	7,578CFS	815.82AC-F	3,217.23AC-F	3,217.23AC-F
6.00	36,600CFS	9,074.38AC-F	286.75FT	0.00FT	21,360CFS	3,207.46AC-F	5,866.91AC-F	5,866.91AC-F
8.00	48,800CFS	16,132.23AC-F	288.63FT	0.00FT	44,363CFS	8,639.17AC-F	7,493.05AC-F	7,493.05AC-F
10.00	42,700CFS	23,694.21AC-F	288.74FT	0.00FT	45,982CFS	16,105.73AC-F	7,588.47AC-F	7,588.47AC-F
12.00	36,600CFS	30,247.93AC-F	288.23FT	0.00FT	38,683CFS	23,102.88AC-F	7,145.05AC-F	7,145.05AC-F
16.00	24,400CFS	40,330.57AC-F	287.31FT	0.00FT	27,140CFS	33,982.88AC-F	6,347.69AC-F	6,347.69AC-F
20.00	12,200CFS	46,380.16AC-F	286.07FT	0.00FT	15,972CFS	41,109.07AC-F	5,271.08AC-F	5,271.08AC-F
24.00	0CFS	48,396.69AC-F	283.83FT	0.00FT	7,976CFS	45,067.64AC-F	3,329.05AC-F	3,329.05AC-F
30.00	0CFS	48,396.69AC-F	281.17FT	0.00FT	1,347CFS	47,379.41AC-F	1,017.27AC-F	1,017.27AC-F
36.00	0CFS	48,396.69AC-F	280.63FT	0.00FT	536CFS	47,846.40AC-F	550.29AC-F	550.29AC-F
48.00	0CFS	48,396.69AC-F	280.25FT	0.00FT	133CFS	48,178.56AC-F	218.12AC-F	218.12AC-F

crest of dam = 695 ft.
crest of dike = 665 ft.
total length = 1360 ft.

APPENDIX E

INFORMATION - NATIONAL INVENTORY OF DAMS



INVENTORY OF DAMS IN THE UNITED STATES

STATE	IDENTITY NUMBER	DIVISION	STATE	COUNTY	CONGR. DIST.	STATE	COUNTY	CONGR. DIST.	NAME	LATITUDE (NORTH)	LONGITUDE (WEST)	REPORT DATE
CT	108	NED	CT	031	05				SAMUEL P SENIOR DAM	4114.9	7321.0	08SEP78

POPULAR NAME	NAME OF IMPOUNDMENT
SAUGATUCK RESERVOIR DAM	SAUGATUCK RESERVOIR

REGION	BASIN	RIVER OR STREAM	NEAREST DOWNSTREAM CITY-TOWN-VILLAGE	DIST FROM DAM (MI.)	POPULATION
01	07	SAUGATUCK RIVER	WESTPORT	7	29500

TYPE OF DAM	YEAR COMPLETED	PURPOSES	STRUC. HEIGHT (FT.)	HYDRAU. HEIGHT (FT.)	IMPOUNDING CAPACITIES		DIST	OWN	FED	R	PRV/FED	SCS	A	VER/DATE
					MAXIMUM (ACRE-FT.)	NORMAL (ACRE-FT.)								
CTPG	1941	S	130	128	42000	37000		N	N		N	N		23AUG78

REMARKS

D/S HAS	SPILLWAY			MAXIMUM DISCHARGE (FT.)	VOLUME OF DAM (CY)	POWER CAPACITY			NAVIGATION LOCKS																		
	CREST LENGTH	TYPE	WIDTH (FT.)			INSTALLED (MW)	PROPOSED (MW)	NO.	LENGTH (FT.)	WIDTH (FT.)	LENGTH (FT.)	WIDTH (FT.)	LENGTH (FT.)	WIDTH (FT.)	LENGTH (FT.)	WIDTH (FT.)											
1	990	U	300	15600																							

OWNER	ENGINEERING BY	CONSTRUCTION BY
BRIDGEPORT HYDRAULIC CO	CLARENCE M BLAIR INC	BRIDGEPORT HYDRAULIC CO

REGULATORY AGENCY			
DESIGN	CONSTRUCTION	OPERATION	MAINTENANCE
NONE	NONE	NONE	NONE

INSPECTION BY	INSPECTION DATE	AUTHORITY FOR INSPECTION
FLAHERTY-GIAVARA, ASSOC, PC	26JUL78	PL 92-367

REMARKS